



Fig. 1. Exterior Before replacing stucco



Fig. 2. Exterior After replacing stucco



Fig.3. Drum before modification



Fig. 4. Drum Showing 2008 Panels and Cornice Mold



Fig. 5. East Elevation Deteriorated Brickwork



Fig. 6. East Elevation Restored Brickwork



Fig.7. Cupola before Restoration



Fig. 8. Cupola following painting and glazing.



Fig. 9. Window Before Restoration



Fig. 10. Window Following Restoration



Fig. 11. Plaster Damage from Rising Damp



Fig. 12. Rusted Conduit, Soft Brick, under Partially Removed Coating



Fig. 13. Spiral Stair with 1960 Balusters



Fig. 14. Spiral Stair with Correct Balusters



Fig. 15. Senate Railing from 1960




Fig. 16. Senate Railing with Correct Configuration



Fig. 17. Senate Dome installed in 1961 Restoration



Fig. 18. Senate Dome with Correct Configuration and Gaslight Reflector



Fig. 19. Senate Carpeting installed in 1961



Fig. 20. Senate Carpet after 2008 Restoration



Fig. 21. House of Representatives Carpet 1961-2005



Fig. 22. House of Representatives Carpet after 2009 Restoration



Fig. 23. Governor's Office 1961-2005 Interpretation



Fig. 24. Governor's Office 2008 Interpretation



Fig. 25. Senate Drapery from 1961-2005



Fig. 26. Senate Drapery Recreated from Shirt Fabric Artifact



Fig. 27. House Drapery from 1961-2005



Fig. 28. House Drapery Recreated from Reporter's Description



Fig. 29. Governor's Drapery from 1961-2005



Fig. 30. Governor's Drapery woven from Museum Collection Artifact



Fig. 31. Governor's Mantle piece from 1961-2005



Fig. 32. Governor's Mantle from Nichols's Design for Governor's Mansion



Fig. 33. Rotunda First Floor Niche Decoration from 1961-2005



Fig. 34. Rotunda Touchieres based on 1916 Photograph



Fig. 35. Third Floor Library 1915 Photo



Fig. 36. Third Floor Library Recreated from Photograph



Fig. 37. Senate/House Doors from 1961-2005



Fig. 38. Glass Doors Recreated in 2008 from Photograph



Fig. 39. Broken Limestone Prior to 2009 Restoration



Fig. 40. Repaired Limestone



Fig. 41. Copper Roof Destroyed by Hurricane Katrina



Fig. 42. Copper Roof Replaced in 2009 Restoration



Fig. 43. Bulls eye Window in Portico before Restoration



Fig. 44. Portico Following 2009 Restoration



Fig. 45. Original Stone Footing Exposed in Elevator Pit



Fig. 46. Exposed face of Original Catahoula Sandstone from Pit



Fig. 47. Pylon Eagle from Archives Museum Collection




Fig. 48. Pylon Eagle Cast from Original Artifact



Fig. 49. Guide Photo (circa 1912) for 2008 Fence and Pylon Reconstruction



Fig. 50. Sidewalk and Fence Following 2009 Restoration



Fig. 51. Structure of Major Dome Showing Deterioration of Wood Members



Fig. 52. Repairs and Strengthening of Dome Ribs and Tension Ring

